

September 2008

Training Manual: KI7600 Series Power Meters

Level 1, V2.0



kingfisher.com.au



Course Contents

- 1. General Features
- 2. Models
- 3. Detector Types
- 4. Instrument Care
- 5. Prepare instrument

- 6. Modes of operation
- 7. Display Modes
- 8. Built in visible laser (KI7601)
- 9. Memory Operation





1./ General Features

- Low skill operation
- Autotest capability
- Autotest compatible with Agilent N series instruments
- Calibrated at multiple wavelengths
- > 1% factory calibration accuracy
- Supplied with calibration certificate
- Industry standard connectors Including SFF

- High contrast LCD display with backlight
- Battery life 190-360 hours
- DC power socket
- Memory
- USB Computer interface
- Test tone detection
- Built in VLS variant (KI7601)
- > 3 year re-calibration interval
- ➢ 3 year warranty





2./ Models

There are two model styles:

- > KI7600: the most popular.
- > KI7601: fitted with a Visible source on left hand port

There are two Computer interface styles:

- Early instruments: RS232 port
- Current instruments: USB Type A port

RS232 & USB models have minor operational differences





3./ Detector Types

Choose detector to suit your application.

InGaAs: Telco & LAN

- Enhanced InGaAs with good response @ 850 nm
- Power Levels of up to +5 dBm
- Most accurate detector type at Telco wavelengths

H series:

High power – CATV, DWDM

- Enhanced H3 with good response @ 850 nm
- Power level configurations of up to +27 dBm
- Filtered InGaAs

Other detector types available for specific wavelength and power requirements.



a./ Typical Detector Spectral responses



kingfisher.com.au



4./ Instrument Care

Keep the instrument in its carry case during storage and transport

- Use only high quality 1.2-1.5 volt batteries. (Do not use lithium batteries)
- For prolonged storage remove batteries.
- > The instrument is resistant to normal dust and moisture, however it is not waterproof.
- > If moisture gets into the instrument, remove batteries & dry it carefully before reuse
- > Where possible, keep instrument away from strong sunlight.
- Clean the instrument case using Iso-Propyl-Alcohol (IPA) or other non solvent cleaning agents.





5./ Prepare Instrument

- a) Hand carry strap
- b) Control buttons
- c) Power supply batteries & external
- d) Turn On / Off
- e) Fit / Remove adaptors
- f) Test cord selection





a./ Hand carry strap

If required, fit provided hand carry strap:

Provides enhanced on-the-job instrument care







c./ Power supply - batteries

AA TO C

To Install Batteries.

- Hold instrument in both hands with battery compartment uppermost and with thumbs resting on battery compartment latch.
- Press latch down and push away from case.
- > Insert batteries.
 - > Insert 'AA' cells using the supplied AA-C battery converters.

Battery life.

Alkaline 'C' batteries : 360 hours meter, 190 hrs VFL Alkaline 'AA' batteries : approx 75 hours meter

Low Battery Display.

Indicator shows when approximately 10 hours left.



tingfisher.com.au



Power Supply - external

All Instruments:

- External power supply disconnects the batteries
- Rechargeable batteries must be removed for charging

a presente

RS232:

> Via the DC power socket

USB:

Via the DC socket or via the USB cord

Plug Pack Requirements:

- > 2.5 mm DC power plug
- 6-12 V DC @ 300 mA maximum
- ➤ +Ve pin





d./ Turn On / Off

10 minutes auto Off or Permanent operation





e./ Adaptor - fitting





Adaptor - removal

Current models:

- > Locate quick release button on rear of instrument at base of connector housing
- Push and hold button in
- > Pull out existing adaptor
- > Fit new adaptor

OR

Remove as per 'early models'

Early models:

- Move adaptor interface to mid position
- Pull out existing adaptor
- > Fit new adaptor





f./ Test cord selection

Power meters accept PC and APC connectors.

KI7601 has built in visible laser source (VLS)Must specify visible source to be PC or APC when ordering

Instrument ports are colour coded: VLS connector:

- > PC housing: **BLUE**
- > APC housing: **GREEN**







6./ Modes of Operation

4 main modes of operation

a) Autotest:

- \succ automatically toggles between all λ s
- > Preferred mode for loss testing as testing time is greatly reduced.
- > Minimises error as meter always displays correct λ .

b) Manual:

- > Single λ operation
- Preferred mode for level monitoring.

c) Modulated:

Displays incoming modulation frequency



ingfisher.com.au





Simplest mode for loss testing

When receiving light from a compliant source operating in Autotest mode, the meter will auto toggle between λs

- Power meter receives <u>data</u> which contains wavelength, source serial number and nominal source output power.
- If power meter not calibrated at an incoming wavelength it will ignore it but remain in sync with other wavelengths.
- If incoming power level too low at a particular wavelength it will ignore it but remain in sync with other wavelengths.



- If not in power meter mode
- Press [Power Meter]
- To select wavelength
- Toggle [-/+].

Note:

- > Wavelength toggle is not circular
- Most meters have the common wavelengths grouped together for speed of access when used in manual mode.
 E.g. 850, 1300, 1310, 1550, 1625 nm are together





c./ Test Tone

When receiving test tone or low level modulation

- > Power meter displays modulated frequency and beeps
- Built in feature cannot be disabled





d./ KITS™

Direct Interface to - KITS[™] Testing & Reporting software Instrument under computer control

10	NGFI	SHE	R KIT	SIM	Live I	Data	Captul	re W	orksh	ieet	
Verson 4.12											
		Job [Details /	Site Da	لموقع ta	، /بیانات ا	فرمن العمل	تفاصبل			
b No R/ backbone I					Project	Raven08 D					
ubject					Stage		Report/F				
ection	M	IIIman R/T	to Green H	401	Duct			Channel			
ircuit ID					Cable	F-THUT-3005 U					
oute		G-THUT-T	11UG-C001		Sheath	Sheath MM-08700054				Other	
ddress "	W.			42 Bark	us Road		Address "B" 86 Cros				
Termin	العماد المارفرد. Terminal ID			th ID	Source type		Source S/N		Meter type		
"A"	TH	IUT			K17	3/13	8855		K173/13		
"B"	TH	UG			KI7343				KI7	343	
	Stati	stical A	nalysis	لإحصائي	التحليل ا		تطبيق المعايين : Applied Standard				
	L	ارة oss	خس		ORL				6	fibers	
λ	Min	Mean	Max	Min	Mean	Max		THUT			
1310	0.01	0.69	2.99	30.21	31.56	33.84					
1550	0.01	2.45	7.34	25.02	28.54	32.81		SCPC	Length		
								op Delay			
نثائج الاغتبان Test Results											
Fiber ID		Insertion			rtion Loss	tion Loss (IL) Results dB					
"A"	"B" ^		Direction A->B		Direc الأكماد		tion B->A_st	Average	I		
THUT	THUG	nm	Ref A	Meas B	IL A->B	Ref B	Meas A	L B->A	L	Margin	
MH7	1	1310	-7.30	-8.13	0.83	0.00	-7.92	7.92	2.99		
		1550	-0.81	-7.89	7.08	0.00	-7.64	1.84	7.34		

Data downloaded from S/N 16503 , Date/Time 080911 1008

0.30

8.43

ibre	Lambda	Reading	Ref	ORL	Kernote Reading	Remote Ref	Remote ORL	Remote S/N
1	1010	-9.3	0.3					17894
1	1550	-9.21	0.22					17894
2	1310	-9.31	0.3					17894
2	1550	-9.07	0.22					17894

- Familiar Excel[™] User Interface
- Inbuilt multi language support
- Memory extract to Excel spreadsheet or CSV file
- One Click Real Time Data Capture
- Standards based & user definable analysis
- Data Logging
- User Customisable reports
- Fee for service user customisation service

0.31



7./ Display Modes

- a) Absolute dBm / Relative dBr mode
- b) Setting the Reference
- c) Log dBm / Linear W mode





a./ Absolute / Relative Mode

Absolute Mode:

Measure actual power level at a particular location – dBm

Relative Mode:

Measure power level 'relative' to a particular location - dBr









Toggle Absolute / Relative Mode

If not in power meter mode: Press [Power Meter] (1)

To enter Relative mode (dBr)

Press [Abs/Rel] (2) \succ

To return to Absolute mode (dBm):

Press [Abs/Rel] (3) \succ





b./ Setting the Reference

Must be in Relative mode dBr not Absolute mode dBm

- Press and hold soft button [Set Ref] for 3 seconds
 - Meter will beep 5 times
 - > Autotest mode: meter will display 'busy' & zero at all incoming wavelengths
 - Manual mode: zero at indicated wavelength
 - Meter will not zero if display is 'Lo'
 - > Referencing is retained at power off.





c./Log/Linear Mode

To enable:

- Open hidden keypad
- RS232: press [dBm/w] (1)
- USB: press [dB/W] (2)

To return to dB mode:

Repeat above key press



- Must be in manual mode to switch between log & linear modes.
- Linear display functions in both Manual & Autotest
- Resets to log (dBm) mode at power off





8./ KI7601 - Visible Laser

To turn On: → Press [Source] (1)

To toggle flashing:➢ Press [Mod] (2)

To turn Off: ➤ Toggle [-/+] (3)









9./ Memory Operation

- a) Memory clear
- b) Memory store
- c) Memory store at a location
- d) Memory recall
- e) Memory extract to computer





a./ Memory clear

Instrument must be in Manual mode, not Autotest Open hidden keypad:

RS232:

Press [CANCEL] and [RECALL MEMORY] simultaneously and <u>hold</u> for a few seconds.
USB:

> Press [MR] and [EXIT] simultaneously and <u>hold</u> for a few seconds.





a./ Memory - Store

RS232:

- Open hidden keypad
- Press [STORE]

USB:

Press [M+]

SOURCE METER SHIFT KHZ LEVEL dBm/w MAX/MIN CANCEL SET SELECT RECALL STORE MEMORY

During Store operation

- Display will blank or display BUSY
- Meter will beep once
- Memory location displayed top right side

A full memory is indicated by a repeating buzzer

In Autotest stores:- All λs transmitted, Absolute Power, Reference value $% \lambda s$ and S/N of the remote unit





c./ Memory – RS232 Store at a location

Exit Autotest Mode: Open hidden keypad

- Press [RECALL MEMORY] (1)
- Toggle [-/+] to desired memory location (2)
- Press [SET] (3)
- When ready Press [STORE] (4)

Note: memory writes continue from this location.

Typical use:

> Match memory location to fibre number





 \succ

 \geq

 \succ

c./ Memory - USB Store at a location

Exit Autotest Mode: Default KHZ Level Max/Min Open hidden keypad P/F dB/W KL-NF RL-Adi Press [MR] (1) MR Set M+ Exit Toggle [-/+] to desired memory location (2) JP Press [Set] (3) 218 mem When ready - Press [M+] (4) dBm >>> Note: memory writes continue from this location. Abs/Rel Hold Menu **Typical use:** Match memory location to fibre number



d./ Memory – Recall – RS232

Exit Autotest Mode Open hidden keypad

RS232:

- Push [RECALL MEMORY] (1)
- > Toggle [-/+] to desired memory location (2) Display alternates between λ and memory number
- > Push [ABS/REL] to alternate between dBr & dBm (3)
 - dBr: Reference shown on LHS of LCD.
 - Hint: Push & hold [ABS/REL] to display reference in display centre.
- > Press [-/+] to scroll λ and memory (2)
- Exit memory display by pressing [CANCEL] (4)





d./ Memory – Recall – USB

Exit Autotest Mode Open hidden keypad

USB:

- Push [MR] (1)
- Toggle [-/+] to desired memory location (2)
 Display alternates between λ and memory number
- Push [ABS/REL] to alternate between dBr & dBm (3)
 - dBr: Reference shown on LHS of LCD.
 - Hint: Push & hold [ABS/REL] to display reference in display centre.
- > Press [-/+] to scroll λ and memory (2)
- Exit memory display by pressing [Exit] (4)





e./ Memory Extract to Computer

Memory retrieve to computer is covered in the KITS[™] training PPT

						101	o Details / Site	e Data						
					Project				Date	late			96/10/91017	
Sta						tage				Report/File No			Report 20071026	
ction					Duct				Channel/P	erm Link		Oth	er	
cut ID					Cahla	ahla				Drawing No				
uto					Sheath				Other					
dress 7			~	I loero	ot,GLU		Addres	5 °U°			0.01	0.41.3701		
	Terminal ID Sheath ID			th IU	Sourc	e tyrpe	Gource G/N	Meter	rtype Mete		r S/N	CAL Y/N	Uperator Mana	
-G	Title	Duilui iy			k17	242	10044	Pd /-	047 10		54.5	T V	Ditell	
	Cohla Daramatare Ontical Daramatare													
		Cap	Maximum	dineral la	anth (re)		Wasalar	opuca	1310	1490	1550	_		
Tiber	Count	6	L = Fiber I	anomeu le anoth	ແລະ	2.0	F = Fiber attenuat	tion dD	0.05	0.24	0.19			
- Liber	Type	052	NS - Num	her of Soli	cong con	4	SL = Solice Jose	dD	0.1	0.1	0.1			
conner.	for type	GC APC	NO - Nor				CT = Connector 1	-2 loss, dD	0.4	n 4	N 4			
Connec	tor type	DIN PC	NC = Num	ber of Con	nectors	2	CL = Connector o	ther loss, dLl	U.4	U.4	U.4			
ference	Method	1 Cord	ND = Num	ber of othe	r Devices	0	DL = Device inser	tion loss, dD	- 4	- 4	4			
ference	Туре	Remule	Test Direct	tion		2-way	UA = Uncertainty	allowance, di	0.6	0.6	0.6			
							Page / Fail Link L	loco, dB	3.13	2.71	2.52			
		Pass	al ail Calcu	Itation			Pass / Fail Chann	iel Lusis, dB	05.00		05.00			
	1.055 -	(F1) + (S	a nasj + (c	ILCI-NCJ-		+ 0A	Pass / Fail URL I	nss nik	3010	3010	30101			
		Stati	stical An	alysis										
		Loss						-		- <i>c</i>		_		
λ	Miri	Mean	Max	Min	- HDG	ər	Lambda	a Read	ding	Ref		Rem	ote S/N	
	0.00	1122	1 11		_		1010	_		~			40540	
	0.00	0.85	4.93	0.00	_	1	1310nm	า -/	(.27	-8	3.13		16549	
		0.65	4 /n		-			_		_				
					-	1	1550nm	า -/	(.16	- /	.88		16549	
								_						
libe	ID	٨				2	1310nm	า -7	7.27	-8	3.13		16549	
-	B		Dir Dal A	ection A		_		_		_				
- UN OIL	21	1210	-22.49	.32.72		2	1550nm	า -7	7.16	-7	.88		16549	
		1490	-23.65	-29.03		-								
		1550	-20.12	-24.02		- 3	1550nm	n -60).95	-7	.88		16549	
						- 4	1310nm	า -39	9.94	-8	3.13		16549	
						-				-				
						- 4	1550nm	n -30).28	-7	.88		16549	
						5	1310nm	n -39	9.93	-8	13		16549	
						Ŭ				Ŭ				
						5	1550nm	n -30) 28	-7	88		16549	
						U			0		.00			
						6	1310nm	n -43	3 18	-8	13		16549	
				U				U			10040			
						6	1550nm	n -41	1 76	-7	88		16540	
						U	1000111			'	.00		10040	

Download to KITS software or to CSF file

KITS:

Familiar Excel[™] user interface

CSV File:

For those who do not use Microsoft Office



Application Notes

Comprehensive selection available at

www.kingfisher.com.au/ApplicationNotes.htm



